


Упор клиновой HS-Hx



Обозначение	$\varnothing r$	$\varnothing R$	H	L	l	h	H_1	L_1	l
HS-H1	5.5	9.5	16	20	10	7	11.7	9.4	5.4
HS-H2	6.6	11	20	25	12.5	8	15.1	10.5	6.5
HS-H3	9	14	24	30	15	9	17.3	13.6	8.5
HS-H4	11	18	35	40	20	11.5	24.6	20	10.5

Пример использования

